

Item 07168

Sito Water Trap is a plastic water trap with a sealing strip for the now discontinued Sito floor gully. The water trap can be removed from the gully for maintenance and cleaning.



Specifications

Sito Water Trap is a plastic water trap with a sealing strip for the now discontinued Sito floor gully. The water trap can be removed from the gully for maintenance and cleaning.

Item Number	07168
Item Color	White
Material	PP